REGION X FREEDENCY RESPONSE TEAM

VERIFICATION OF SITE FILE REVIEW

Facility Name: 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
City: Mampa
State: Od-
Nature of Problem: Company in involved in the manufaction of metal oxide
silicon microprocessor chips. Wartes from greations include amenic tionis.
liquid moreing comported flammable waster trickly orthoge and action. Wester are otored on sile although labeling record keeping storage and transportation violations and docume
stored on site although labeling, record keeping, storage and transports tion wie laters an docume
Potential for Immediate Removal/Investigation YES NO 77//(
Reviewer Review Date
EPA Emergency Response Team:
Technical Assistance Team: But Hade 14 Manch 1885
Date File Returned to EPA by TAT: 15 Manch (985
IDD Reference File: 10840104- PCS * 3648
Comments: Site is a RCRA controlled facility, an notice of Mineston
and Warning Little was sent to Diloy by EPG in June 1984 waster
and Warning Little was sent to Dilog by EPG in June 1984 waster we stored on site temporarily and then transported to an approved TSD pailing
USEDA SE

1643322